

ISL31495EIUZ-T7A

ISL31495EIUZ-T7A Information

www.hartener.com	 ISL31495EIUZ-T7A Renesas Electronics America Integrated Circuits (ICs) Interface - Drivers, Receivers, Transceivers IC TXRX RS485 FAULT PROT 8MSOP 8-TSSOP, 8-MSOP (0.118", 3.00mm Width) For the pricing/inventory/lead time, please contact us	
For Reference Only	Website: https://www.heisener.com E-mail: salesdept@heisener.com	Request a Quote

Certified Quality

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.



ISL31495EIUZ-T7A Specifications

Manufacturer Part Number	ISL31495EIUZ-T7A
Manufacturer	Renesas Electronics America
Category	Integrated Circuits (ICs)
	Interface - Drivers, Receivers, Transceivers
Package	8-TSSOP, 8-MSOP (0.118", 3.00mm Width)
Series	-
Туре	Transceiver
Protocol	RS422, RS485
Number of Drivers/Receivers	1/1
Duplex	Half
Receiver Hysteresis	25mV
Data Rate	1Mbps
Voltage - Supply	4.5 V ~ 5.5 V
Operating Temperature	$-40^{\circ}\mathrm{C} \sim 85^{\circ}\mathrm{C}$
Mounting Type	Surface Mount
Package / Case	8-TSSOP, 8-MSOP (0.118", 3.00mm Width)
Supplier Device Package	8-MSOP
	Report errors?

ISL31495EIUZ-T7A Guarantees



Quality Guarantees

We provide 90 days warranty. * If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.

SERVICE BUARANTEE

Service Guarantees

We guarantee 100% customer satisfaction. Our experienced sales team and tech support team back our services to satisfy all our customers.

DISCOVER

ISL31495EIUZ-T7A Payment Methods



ISL31495EIUZ-T7A Shipping Methods



If you have any question about ISL31495EIUZ-T7A, please do not hesitate to contact us! Website: https://www.heisener.com E-mail: salesdept@heisener.com