



ISL31496EIUZ-T7A Information



For Reference Only

Part Number ISL31496EIUZ-T7A

ManufacturerRenesas Electronics AmericaCategoryIntegrated Circuits (ICs)

Interface - Drivers, Receivers, Transceivers

DescriptionIC TXRX RS485 FAULT PROT 10MSOP**Package**10-TFSOP, 10-MSOP (0.118", 3.00mm Width)

For the pricing/inventory/lead time, please contact

us

Website: https://www.heisener.com E-mail: salesdept@heisener.com



Request a Quote

Certified Quality

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.









ISL31496EIUZ-T7A Specifications

Manufacturer Part Number	ISL31496EIUZ-T7A
Manufacturer	Renesas Electronics America
Category	Integrated Circuits (ICs)
	Interface - Drivers, Receivers, Transceivers
Package	10-TFSOP, 10-MSOP (0.118", 3.00mm Width)
Series	-
Туре	Transceiver
Protocol	RS422, RS485
Number of Drivers/Receivers	1/1
Duplex	Full
Receiver Hysteresis	25mV
Data Rate	15Mbps
Voltage - Supply	4.5 V ~ 5.5 V
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Package / Case	10-TFSOP, 10-MSOP (0.118", 3.00mm Width)
Supplier Device Package	10-MSOP
	Report errors?

ISL31496EIUZ-T7A Guarantees



Quality Guarantees

We provide 90 days warranty. *

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



Service Guarantees

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

ISL31496EIUZ-T7A Payment Methods



















ISL31496EIUZ-T7A Shipping Methods













If you have any question about ISL31496EIUZ-T7A, please do not hesitate to contact us!

Website: https://www.heisener.com E-mail: salesdept@heisener.com