

## ISL88706IB844Z-TK

#### ISL88706IB844Z-TK Information



For Reference Only

Part Number ISL88706IB844Z-TK

ManufacturerRenesas Electronics AmericaCategoryIntegrated Circuits (ICs)

PMIC - Supervisors

**Description** IC SUPERVISOR MPU 4.38V 8-SOIC

**Package** 8-SOIC (0.154", 3.90mm Width)

For the pricing/inventory/lead time, please contact

us

Website: https://www.heisener.com E-mail: salesdept@heisener.com



Request a Quote

# **Certified Quality**

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.









### ISL88706IB844Z-TK Specifications

M. C. A. D. AM. I	ICI 0070 (ID 0 447 TW
Manufacturer Part Number	ISL88706IB844Z-TK
Manufacturer	Renesas Electronics America
Category	Integrated Circuits (ICs)
	PMIC - Supervisors
Package	8-SOIC (0.154", 3.90mm Width)
Series	-
Type	Simple Reset/Power-On Reset
Number of Voltages Monitored	1
Output	Open Drain or Open Collector
Reset	Active Low
Reset Timeout	140 ms Minimum
Voltage - Threshold	4.38V
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Package / Case	8-SOIC (0.154", 3.90mm Width)
Supplier Device Package	8-SOIC
	Report errors?

#### ISL88706IB844Z-TK Guarantees



#### **Quality Guarantees**

We provide 90 days warranty. \*

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



#### **Service Guarantees**

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

### ISL88706IB844Z-TK Payment Methods



















## ISL88706IB844Z-TK Shipping Methods













If you have any question about ISL88706IB844Z-TK, please do not hesitate to contact us!

Website: https://www.heisener.com E-mail: salesdept@heisener.com