

LD15S13A4GX00LF

LD15S13A4GX00LF Information

Heisener.com	Part Number	LD15S13A4GX00LF	
	Manufacturer	Amphenol FCI	fails the
	Category	Connectors, Interconnects D-Sub Connectors	
	Description	CONN D-SUB RCPT 15POS R/A SOLDER	2.2
	Package	-	
		For the pricing/inventory/lead time, please contact	E stra
For Reference Only		us Website: https://www.heisener.com E-mail: salesdept@heisener.com	Request a

Certified Quality

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.



Quote

LD15S13A4GX00LF Specifications

LD15S13A4GX00LF
Amphenol FCI
Connectors, Interconnects
D-Sub Connectors
-
LD
D-Sub
Receptacle, Female Sockets
15
2
2 (DA, A)
Signal
Board Edge, Through Hole, Right Angle
Housing/Shell (4-40)
Solder
Board Lock
Nickel, Tin Plated
Gold
Flash
-
UL94 V-0
Report errors?

LD15S13A4GX00LF Guarantees



Quality Guarantees

We provide 90 days warranty. * If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.

SERVICE BUARANTEE

Service Guarantees

We guarantee 100% customer satisfaction. Our experienced sales team and tech support team back our services to satisfy all our customers.

LD15S13A4GX00LF Payment Methods





If you have any question about LD15S13A4GX00LF, please do not hesitate to contact us! Website: https://www.heisener.com E-mail: salesdept@heisener.com