

LM8364BALMF30/NOPB

LM8364BALMF30/NOPB Information



Part Number	LM8364BALMF30/NOPB
Manufacturer	Texas Instruments
Category	Integrated Circuits (ICs) PMIC - Supervisors
Description	IC DETECT UNDERVOLT 3V SOT-23-5
Package	SC-74A, SOT-753
	For the pricing/inventory/lead time, please contact us Website: https://www.heisener.com E-mail: salesdept@heisener.com



Request a Quote

For Reference Only

Certified Quality

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.



LM8364BALMF30/NOPB Specifications

Manufacturer Part Number	LM8364BALMF30/NOPB
Manufacturer	Texas Instruments
Category	Integrated Circuits (ICs)
	PMIC - Supervisors
Package	SC-74A, SOT-753
Series	-
Туре	Simple Reset/Power-On Reset
Number of Voltages Monitored	1
Output	Open Drain or Open Collector
Reset	Active Low
Reset Timeout	60 µs Typical Propagation Delay
Voltage - Threshold	3V
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Package / Case	SC-74A, SOT-753
Supplier Device Package	SOT-23-5
	Report errors?

LM8364BALMF30/NOPB Guarantees



Quality Guarantees

We provide 90 days warranty. * If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



Service Guarantees

We guarantee 100% customer satisfaction. Our experienced sales team and tech support team back our services to satisfy all our customers.

LM8364BALMF30/NOPB Payment Methods



If you have any question about LM8364BALMF30/NOPB, please do not hesitate to contact us! Website: https://www.heisener.com E-mail: salesdept@heisener.com