

**LM8364BALMFX20 Information**


For Reference Only

**Part Number** [LM8364BALMFX20](#)  
**Manufacturer** Texas Instruments  
**Category** Integrated Circuits (ICs)  
[PMIC - Supervisors](#)  
**Description** IC DETECTOR UNDERVOLT 2V SOT23-5  
**Package** SC-74A, SOT-753  
 For the pricing/inventory/lead time, please contact us  
 Website: <https://www.heisener.com>  
 E-mail: [salesdept@heisener.com](mailto:salesdept@heisener.com)


[Request a Quote](#)
**Certified Quality**

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.


**LM8364BALMFX20 Specifications**

Manufacturer Part Number	<a href="#">LM8364BALMFX20</a>
Manufacturer	Texas Instruments
Category	Integrated Circuits (ICs) <a href="#">PMIC - Supervisors</a>
Package	SC-74A, SOT-753
Series	-
Type	Simple Reset/Power-On Reset
Number of Voltages Monitored	1
Output	Open Drain or Open Collector
Reset	Active Low
Reset Timeout	60 $\mu$ s Typical Propagation Delay
Voltage - Threshold	2V
Operating Temperature	-40°C ~ 85°C (TA)
Mounting Type	Surface Mount
Package / Case	SC-74A, SOT-753
Supplier Device Package	SOT-23-5
<a href="#">Report errors?</a>	

## LM8364BALMFX20 Guarantees



### Quality Guarantees

We provide 90 days warranty. \*

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



### Service Guarantees

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

## LM8364BALMFX20 Payment Methods



## LM8364BALMFX20 Shipping Methods



If you have any question about LM8364BALMFX20, please do not hesitate to contact us!

Website: <https://www.heisener.com>

E-mail: [salesdept@heisener.com](mailto:salesdept@heisener.com)