

LM8364BALMFX20 Information


For Reference Only

Part Number [LM8364BALMFX20](#)
Manufacturer Texas Instruments
Category Integrated Circuits (ICs)
 [PMIC - Supervisors](#)
Description IC DETECTOR UNDERVOLT 2V SOT23-5
Package SC-74A, SOT-753
 For the pricing/inventory/lead time, please contact us
 Website: <https://www.heisener.com>
 E-mail: salesdept@heisener.com


[Request a Quote](#)
Certified Quality

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.


LM8364BALMFX20 Specifications

| | |
|------------------------------|---|
| Manufacturer Part Number | LM8364BALMFX20 |
| Manufacturer | Texas Instruments |
| Category | Integrated Circuits (ICs) PMIC - Supervisors |
| Package | SC-74A, SOT-753 |
| Series | - |
| Type | Simple Reset/Power-On Reset |
| Number of Voltages Monitored | 1 |
| Output | Open Drain or Open Collector |
| Reset | Active Low |
| Reset Timeout | 60 μ s Typical Propagation Delay |
| Voltage - Threshold | 2V |
| Operating Temperature | -40°C ~ 85°C (TA) |
| Mounting Type | Surface Mount |
| Package / Case | SC-74A, SOT-753 |
| Supplier Device Package | SOT-23-5 |

[Report errors?](#)

LM8364BALMFX20 Guarantees



Quality Guarantees

We provide 90 days warranty. *

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



Service Guarantees

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

LM8364BALMFX20 Payment Methods



LM8364BALMFX20 Shipping Methods



If you have any question about LM8364BALMFX20, please do not hesitate to contact us!

Website: <https://www.heisener.com>

E-mail: salesdept@heisener.com