

**LP3470IM5-2.93 Information**


For Reference Only

**Part Number** [LP3470IM5-2.93](#)  
**Manufacturer** Texas Instruments  
**Category** Integrated Circuits (ICs)  
           [PMIC - Supervisors](#)  
**Description** IC CIRCUIT RESET PWR-ON SOT23-5  
**Package** SC-74A, SOT-753  
 For the pricing/inventory/lead time, please contact us  
 Website: <https://www.heisener.com>  
 E-mail: [salesdept@heisener.com](mailto:salesdept@heisener.com)


[Request a Quote](#)
**Certified Quality**

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.


**LP3470IM5-2.93 Specifications**

|                              |   |
|------------------------------|---|
| Manufacturer Part Number     | <a href="#">LP3470IM5-2.93</a>                                  |
| Manufacturer                 | Texas Instruments   |
| Category                     | Integrated Circuits (ICs)<br><a href="#">PMIC - Supervisors</a> |
| Package                      | SC-74A, SOT-753   |
| Series                       | -   |
| Type                         | Simple Reset/Power-On Reset                                     |
| Number of Voltages Monitored | 1   |
| Output                       | Open Drain or Open Collector                                    |
| Reset                        | Active Low  |
| Reset Timeout                | 1 ms Minimum  |
| Voltage - Threshold          | 2.93V   |
| Operating Temperature        | -40°C ~ 85°C (TJ)   |
| Mounting Type                | Surface Mount   |
| Package / Case               | SC-74A, SOT-753   |
| Supplier Device Package      | SOT-23-5  |

[Report errors?](#)

## LP3470IM5-2.93 Guarantees



### Quality Guarantees

We provide 90 days warranty. \*

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



### Service Guarantees

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

## LP3470IM5-2.93 Payment Methods



## LP3470IM5-2.93 Shipping Methods



If you have any question about LP3470IM5-2.93, please do not hesitate to contact us!

Website: <https://www.heisener.com>

E-mail: [salesdept@heisener.com](mailto:salesdept@heisener.com)