

LP3470IM5X-2.63/NOPB

LP3470IM5X-2.63/NOPB Information



| Part Number | LP3470IM5X-2.63/NOPB |
|--------------|--|
| Manufacturer | Texas Instruments |
| Category | Integrated Circuits (ICs) PMIC - Supervisors |
| Description | IC CIRCUIT TNY PWR RESET SOT23-5 |
| Package | SC-74A, SOT-753 |
| | For the pricing/inventory/lead time, please contact us Website: https://www.heisener.com E-mail: salesdept@heisener.com |



Request a Quote

For Reference Only

Certified Quality

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.



LP3470IM5X-2.63/NOPB Specifications

| Manufacturer Part Number | LP3470IM5X-2.63/NOPB |
|------------------------------|------------------------------|
| Manufacturer | Texas Instruments |
| Category | Integrated Circuits (ICs) |
| | PMIC - Supervisors |
| Package | SC-74A, SOT-753 |
| Series | - |
| Туре | Simple Reset/Power-On Reset |
| Number of Voltages Monitored | 1 |
| Output | Open Drain or Open Collector |
| Reset | Active Low |
| Reset Timeout | 1 ms Minimum |
| Voltage - Threshold | 2.63V |
| Operating Temperature | -40°C ~ 85°C (TJ) |
| Mounting Type | Surface Mount |
| Package / Case | SC-74A, SOT-753 |
| Supplier Device Package | SOT-23-5 |
| | Report errors? |

LP3470IM5X-2.63/NOPB Guarantees



Quality Guarantees

We provide 90 days warranty. * If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



Service Guarantees

We guarantee 100% customer satisfaction. Our experienced sales team and tech support team back our services to satisfy all our customers.

LP3470IM5X-2.63/NOPB Payment Methods





If you have any question about LP3470IM5X-2.63/NOPB, please do not hesitate to contact us! Website: https://www.heisener.com E-mail: salesdept@heisener.com