

MAX708RCPA+

MAX708RCPA+ Information

| erener.com | | MAX708RCPA+ Maxim Integrated | in 178 in 1 |
|--------------------|-------------|---|--------------------|
| | Category | Integrated Circuits (ICs) PMIC - Supervisors | |
| | Description | IC SUPERVISOR MPU 8-DIP | - 849 8 587 |
| | Package | 8-DIP (0.300", 7.62mm) | |
| | | For the pricing/inventory/lead time, please contact us | E12/06/2 |
| For Reference Only | | Website: https://www.heisener.com E-mail: salesdept@heisener.com | Request a Quote |

Certified Quality

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.



MAX708RCPA+ Specifications

| Manufacturer Part Number | MAX708RCPA+ |
|------------------------------|-----------------------------|
| Manufacturer | Maxim Integrated |
| Category | Integrated Circuits (ICs) |
| | PMIC - Supervisors |
| Package | 8-DIP (0.300", 7.62mm) |
| Series | - |
| Туре | Simple Reset/Power-On Reset |
| Number of Voltages Monitored | 1 |
| Output | Push-Pull, Push-Pull |
| Reset | Active High/Active Low |
| Reset Timeout | 140 ms Minimum |
| Voltage - Threshold | 2.63V |
| Operating Temperature | 0°C ~ 70°C (TA) |
| Mounting Type | Through Hole |
| Package / Case | 8-DIP (0.300", 7.62mm) |
| Supplier Device Package | 8-PDIP |
| | Report errors |

MAX708RCPA+ Guarantees



Quality Guarantees

We provide 90 days warranty. * If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.

SERVICE EUARANTEE

Service Guarantees

We guarantee 100% customer satisfaction. Our experienced sales team and tech support team back our services to satisfy all our customers.

MAX708RCPA+ Payment Methods



MAX708RCPA+ Shipping Methods



If you have any question about MAX708RCPA+, please do not hesitate to contact us! Website: https://www.heisener.com E-mail: salesdept@heisener.com