

MBA02040C1808FRP00

MBA02040C1808FRP00 Information



For Reference Only

Part Number MBA02040C1808FRP00 Manufacturer Vishay BC Components

Category Resistors

Through Hole Resistors

Description RES 1.8 OHM 0.4W 1% AXIAL

Package Axia

For the pricing/inventory/lead time, please contact

us

Website: https://www.heisener.com E-mail: salesdept@heisener.com



Request a Quote

Certified Quality

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.









MBA02040C1808FRP00 Specifications

Manuela ataun Dart Manulan	MD 4 020 40C1 000 ED D00
Manufacturer Part Number	MBA02040C1808FRP00
Manufacturer	Vishay BC Components
Category	Resistors
	Through Hole Resistors
Package	Axial
Series	MBA/SMA 0204 - Professional
Resistance	1.8 Ohms
Tolerance	±1%
Power (Watts)	0.4W
Composition	Thin Film
Features	-
Temperature Coefficient	±50ppm/°C
Operating Temperature	-55°C ~ 155°C
Package / Case	Axial
Supplier Device Package	Axial
Size / Dimension	0.063" Dia x 0.142" L (1.60mm x 3.60mm)
Height - Seated (Max)	-
Number of Terminations	2
Failure Rate	-
	Report errors?

MBA02040C1808FRP00 Guarantees



Quality Guarantees

We provide 90 days warranty. *

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



Service Guarantees

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

MBA02040C1808FRP00 Payment Methods



















MBA02040C1808FRP00 Shipping Methods













If you have any question about MBA02040C1808FRP00, please do not hesitate to contact us!

Website: https://www.heisener.com E-mail: salesdept@heisener.com