


# MBA02040C2491FC100

#### MBA02040C2491FC100 Information



For Reference Only

Part Number MBA02040C2491FC100 Manufacturer Vishay BC Components

**Category** Resistors

Through Hole Resistors

**Description** RES 2.49K OHM 0.4W 1% AXIAL

Package Axia

For the pricing/inventory/lead time, please contact

us

Website: https://www.heisener.com E-mail: salesdept@heisener.com



Request a Quote

# **Certified Quality**

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.









# MBA02040C2491FC100 Specifications

	Report errors?
Failure Rate	-
Number of Terminations	2
Height - Seated (Max)	-
Size / Dimension	0.063" Dia x 0.142" L (1.60mm x 3.60mm)
Supplier Device Package	-
Package / Case	Axial
Operating Temperature	-55°C ~ 155°C
Temperature Coefficient	±50ppm/°C
Features	Automotive AEC-Q200
Composition	Thin Film
Power (Watts)	0.4W
Tolerance	±1%
Resistance	2.49 kOhms
Series	MBA/SMA 0204 - Professional
Package	Axial
	Through Hole Resistors
Category	Resistors
Manufacturer	Vishay BC Components
Manufacturer Part Number	MBA02040C2491FC100

#### MBA02040C2491FC100 Guarantees



## **Quality Guarantees**

We provide 90 days warranty. \*

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



#### **Service Guarantees**

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

### MBA02040C2491FC100 Payment Methods



















## MBA02040C2491FC100 Shipping Methods













If you have any question about MBA02040C2491FC100, please do not hesitate to contact us!

Website: https://www.heisener.com E-mail: salesdept@heisener.com