


MBA02040C2871FC100 Information


For Reference Only

Part Number [MBA02040C2871FC100](#)
Manufacturer Vishay BC Components
Category Resistors
 [Through Hole Resistors](#)
Description RES 2.87K OHM 0.4W 1% AXIAL
Package Axial
 For the pricing/inventory/lead time, please contact us
 Website: <https://www.heisener.com>
 E-mail: salesdept@heisener.com


[Request a Quote](#)
Certified Quality

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.


MBA02040C2871FC100 Specifications

| | |
|--------------------------|---|
| Manufacturer Part Number | MBA02040C2871FC100 |
| Manufacturer | Vishay BC Components |
| Category | Resistors Through Hole Resistors |
| Package | Axial |
| Series | MBA/SMA 0204 - Professional |
| Resistance | 2.87 kOhms |
| Tolerance | ±1% |
| Power (Watts) | 0.4W |
| Composition | Thin Film |
| Features | Automotive AEC-Q200 |
| Temperature Coefficient | ±50ppm/°C |
| Operating Temperature | -55°C ~ 155°C |
| Package / Case | Axial |
| Supplier Device Package | - |
| Size / Dimension | 0.063" Dia x 0.142" L (1.60mm x 3.60mm) |
| Height - Seated (Max) | - |
| Number of Terminations | 2 |
| Failure Rate | - |

[Report errors?](#)

MBA02040C2871FC100 Guarantees



Quality Guarantees

We provide 90 days warranty. *

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



Service Guarantees

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

MBA02040C2871FC100 Payment Methods



MBA02040C2871FC100 Shipping Methods



If you have any question about MBA02040C2871FC100, please do not hesitate to contact us!

Website: <https://www.heisener.com>

E-mail: salesdept@heisener.com