


MBA02040C3323FC100

MBA02040C3323FC100 Information



Certified Quality

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.



MBA02040C3323FC100 Specifications

| | Report errors? |
|--------------------------|---|
| Failure Rate | - |
| Number of Terminations | 2 |
| Height - Seated (Max) | - |
| Size / Dimension | 0.063" Dia x 0.142" L (1.60mm x 3.60mm) |
| Supplier Device Package | - |
| Package / Case | Axial |
| Operating Temperature | -55°C ~ 155°C |
| Temperature Coefficient | ±50ppm/°C |
| Features | - |
| Composition | Thin Film |
| Power (Watts) | 0.4W |
| Tolerance | $\pm 1\%$ |
| Resistance | 332 kOhms |
| Series | MBA/SMA 0204 - Professional |
| Package | Axial |
| | Through Hole Resistors |
| Category | Resistors |
| Manufacturer | Vishay BC Components |
| Manufacturer Part Number | MBA02040C3323FC100 |

MBA02040C3323FC100 Guarantees



Quality Guarantees

We provide 90 days warranty. * If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



Service Guarantees

We guarantee 100% customer satisfaction. Our experienced sales team and tech support team back our services to satisfy all our customers.

MBA02040C3323FC100 Payment Methods





If you have any question about MBA02040C3323FC100, please do not hesitate to contact us! Website: https://www.heisener.com E-mail: salesdept@heisener.com