


**MBA02040C3907JC100 Information**


For Reference Only

**Part Number** [MBA02040C3907JC100](#)  
**Manufacturer** Vishay BC Components  
**Category** Resistors  
     [Through Hole Resistors](#)  
**Description** RES 0.39 OHM 0.4W 5% AXIAL  
**Package** Axial  
 For the pricing/inventory/lead time, please contact us  
 Website: <https://www.heisener.com>  
 E-mail: [salesdept@heisener.com](mailto:salesdept@heisener.com)


[Request a Quote](#)
**Certified Quality**

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.


**MBA02040C3907JC100 Specifications**

|                          |   |
|--------------------------|---|
| Manufacturer Part Number | <a href="#">MBA02040C3907JC100</a>                  |
| Manufacturer             | Vishay BC Components                                |
| Category                 | Resistors<br><a href="#">Through Hole Resistors</a> |
| Package                  | Axial   |
| Series                   | MBA/SMA 0204 - Professional                         |
| Resistance               | 390 mOhms   |
| Tolerance                | ±5%   |
| Power (Watts)            | 0.4W  |
| Composition              | Thin Film   |
| Features                 | -   |
| Temperature Coefficient  | ±50ppm/°C   |
| Operating Temperature    | -55°C ~ 155°C                                       |
| Package / Case           | Axial   |
| Supplier Device Package  | -   |
| Size / Dimension         | 0.063" Dia x 0.142" L (1.60mm x 3.60mm)             |
| Height - Seated (Max)    | -   |
| Number of Terminations   | 2   |
| Failure Rate             | -   |

[Report errors?](#)

## MBA02040C3907JC100 Guarantees



### Quality Guarantees

We provide 90 days warranty. \*

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



### Service Guarantees

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

## MBA02040C3907JC100 Payment Methods



## MBA02040C3907JC100 Shipping Methods



If you have any question about MBA02040C3907JC100, please do not hesitate to contact us!

Website: <https://www.heisener.com>

E-mail: [salesdept@heisener.com](mailto:salesdept@heisener.com)