

MBA02040C4871FC100

MBA02040C4871FC100 Information



For Reference Only

Part Number MBA02040C4871FC100 Manufacturer Vishay BC Components

Category Resistors

Through Hole Resistors

Description RES 4.87K OHM 0.4W 1% AXIAL

Package Axia

For the pricing/inventory/lead time, please contact

us

Website: https://www.heisener.com E-mail: salesdept@heisener.com



Request a Quote

Certified Quality

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.









MBA02040C4871FC100 Specifications

| Manufacturer Part Number | MBA02040C4871FC100 |
|--------------------------|---|
| Manufacturer | Vishay BC Components |
| Category | Resistors |
| | Through Hole Resistors |
| Package | Axial |
| Series | MBA/SMA 0204 - Professional |
| Resistance | 4.87 kOhms |
| Tolerance | ±1% |
| Power (Watts) | 0.4W |
| Composition | Thin Film |
| Features | Automotive AEC-Q200 |
| Temperature Coefficient | ±50ppm/°C |
| Operating Temperature | -55°C ~ 155°C |
| Package / Case | Axial |
| Supplier Device Package | - |
| Size / Dimension | 0.063" Dia x 0.142" L (1.60mm x 3.60mm) |
| Height - Seated (Max) | - |
| Number of Terminations | 2 |
| Failure Rate | - |
| | Report errors? |

MBA02040C4871FC100 Guarantees



Quality Guarantees

We provide 90 days warranty. *

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



Service Guarantees

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

MBA02040C4871FC100 Payment Methods



















MBA02040C4871FC100 Shipping Methods













If you have any question about MBA02040C4871FC100, please do not hesitate to contact us!

Website: https://www.heisener.com E-mail: salesdept@heisener.com