


**MBA02040D3302FC100 Information**


For Reference Only

**Part Number** [MBA02040D3302FC100](#)  
**Manufacturer** Vishay BC Components  
**Category** Resistors  
     [Through Hole Resistors](#)  
**Description** RES 33K OHM 0.4W 1% AXIAL  
**Package** Axial  
 For the pricing/inventory/lead time, please contact us  
 Website: <https://www.heisener.com>  
 E-mail: [salesdept@heisener.com](mailto:salesdept@heisener.com)


[Request a Quote](#)
**Certified Quality**

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.


**MBA02040D3302FC100 Specifications**

Manufacturer Part Number	<a href="#">MBA02040D3302FC100</a>
Manufacturer	Vishay BC Components
Category	Resistors <a href="#">Through Hole Resistors</a>
Package	Axial
Series	MBA/SMA 0204 - Professional
Resistance	33 kOhms
Tolerance	±1%
Power (Watts)	0.4W
Composition	Thin Film
Features	-
Temperature Coefficient	±25ppm/°C
Operating Temperature	-55°C ~ 155°C
Package / Case	Axial
Supplier Device Package	-
Size / Dimension	0.063" Dia x 0.142" L (1.60mm x 3.60mm)
Height - Seated (Max)	-
Number of Terminations	2
Failure Rate	-

[Report errors?](#)

## MBA02040D3302FC100 Guarantees



### Quality Guarantees

We provide 90 days warranty. \*

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



### Service Guarantees

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

## MBA02040D3302FC100 Payment Methods



## MBA02040D3302FC100 Shipping Methods



If you have any question about MBA02040D3302FC100, please do not hesitate to contact us!

Website: <https://www.heisener.com>

E-mail: [salesdept@heisener.com](mailto:salesdept@heisener.com)