

MC100ES6111FAR2 Information


For Reference Only

Part Number [MC100ES6111FAR2](#)
Manufacturer NXP
Category Integrated Circuits (ICs)
[Clock/Timing - Clock Buffers, Drivers](#)
Description IC CLK BUFFER 2:10 2.7GHZ 32LQFP
Package 32-LQFP
 For the pricing/inventory/lead time, please contact us
 Website: <https://www.heisener.com>
 E-mail: salesdept@heisener.com


[Request a Quote](#)
Certified Quality

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.


MC100ES6111FAR2 Specifications

Manufacturer Part Number	MC100ES6111FAR2
Manufacturer	NXP
Category	Integrated Circuits (ICs) Clock/Timing - Clock Buffers, Drivers
Package	32-LQFP
Series	100ES
Type	Fanout Buffer (Distribution), Multiplexer
Number of Circuits	1
Ratio - Input:Output	2:10
Differential - Input:Output	Yes/Yes
Input	ECL, HSTL, PECL
Output	ECL, PECL
Frequency - Max	2.7GHz
Voltage - Supply	2.375 V ~ 3.465 V
Operating Temperature	-40°C ~ 110°C
Mounting Type	Surface Mount
Package / Case	32-LQFP
Supplier Device Package	32-LQFP (9x9)

[Report errors?](#)

MC100ES6111FAR2 Guarantees



Quality Guarantees

We provide 90 days warranty. *

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



Service Guarantees

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

MC100ES6111FAR2 Payment Methods



MC100ES6111FAR2 Shipping Methods



If you have any question about MC100ES6111FAR2, please do not hesitate to contact us!

Website: <https://www.heisener.com>

E-mail: salesdept@heisener.com