

MC33972EWR2

uest a Quote

MC33972EWR2 Information

| Www.helsener.com | Part Number | MC33972EWR2 | |
|--------------------|--------------|---|-------|
| | Manufacturer | | |
| | Category | Integrated Circuits (ICs) Interface - Specialized | |
| | Description | IC SWITCH DETECT SPI 32-SOIC | - 38F |
| | Package | 32-SOIC (0.295", 7.50mm Width) | |
| | | For the pricing/inventory/lead time, please contact us | |
| For Reference Only | | Website: https://www.heisener.com E-mail: salesdept@heisener.com | Requ |

Certified Quality

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.



MC33972EWR2 Specifications

| Manufacturer Part Number | MC33972EWR2 |
|--------------------------|--------------------------------|
| Manufacturer | NXP |
| Category | Integrated Circuits (ICs) |
| | Interface - Specialized |
| Package | 32-SOIC (0.295", 7.50mm Width) |
| Series | - |
| Applications | Switch Monitoring |
| Interface | SPI Serial |
| Voltage - Supply | 3.1 V ~ 5.25 V |
| Package / Case | 32-SOIC (0.295", 7.50mm Width) |
| Supplier Device Package | 32-SOIC |
| Mounting Type | Surface Mount |
| | Report errors? |

MC33972EWR2 Guarantees



Quality Guarantees

We provide 90 days warranty. * If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



Service Guarantees We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.



If you have any question about MC33972EWR2, please do not hesitate to contact us! Website: https://www.heisener.com E-mail: salesdept@heisener.com