

PCK9447BD,151 Information


For Reference Only

Part Number [PCK9447BD,151](#)
Manufacturer NXP
Category Integrated Circuits (ICs)
[Clock/Timing - Clock Buffers, Drivers](#)
Description IC CLK BUFFER 2:9 350MHZ 32LQFP
Package 32-LQFP
 For the pricing/inventory/lead time, please contact us
 Website: <https://www.heisener.com>
 E-mail: salesdept@heisener.com


[Request a Quote](#)
Certified Quality

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.


PCK9447BD,151 Specifications

Manufacturer Part Number	PCK9447BD,151
Manufacturer	NXP
Category	Integrated Circuits (ICs) Clock/Timing - Clock Buffers, Drivers
Package	32-LQFP
Series	-
Type	Fanout Buffer (Distribution), Multiplexer
Number of Circuits	1
Ratio - Input:Output	2:9
Differential - Input:Output	No/No
Input	LVC MOS
Output	LVC MOS
Frequency - Max	350MHz
Voltage - Supply	2.375 V ~ 3.465 V
Operating Temperature	-40°C ~ 85°C
Mounting Type	Surface Mount
Package / Case	32-LQFP
Supplier Device Package	32-LQFP (7x7)

[Report errors?](#)

PCK9447BD,151 Guarantees



Quality Guarantees

We provide 90 days warranty. *

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



Service Guarantees

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

PCK9447BD,151 Payment Methods



PCK9447BD,151 Shipping Methods



If you have any question about PCK9447BD,151, please do not hesitate to contact us!

Website: <https://www.heisener.com>

E-mail: salesdept@heisener.com