

PFST.420 Information


For Reference Only

Part Number PFST.420
Manufacturer Schurter Inc.
Category Circuit Protection
PTC Resettable Fuses
Description FUSE PTC 4.20A 30V RESET AXIAL
Package Strap
 For the pricing/inventory/lead time, please contact us
 Website: <https://www.heisener.com>
 E-mail: salesdept@heisener.com



[Request a Quote](#)

Certified Quality

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.


PFST.420 Specifications

Manufacturer Part Number	PFST.420
Manufacturer	Schurter Inc.
Category	Circuit Protection PTC Resettable Fuses
Package	Strap
Series	PFST
Type	Polymeric
Voltage - Max	30V
Current - Max	100A
Current - Hold (Ih) (Max)	4.2A
Current - Trip (It)	7.6A
Time to Trip	6s
Resistance - Initial (Ri) (Min)	12 mOhms
Resistance - Post Trip (R1) (Max)	40 mOhms
Resistance - 25°C (Typ)	-
Operating Temperature	-40°C ~ 85°C
Ratings	-
Mounting Type	User Defined
Package / Case	Strap
Size / Dimension	1.240" L x 0.522" W (31.50mm x 13.25mm)
Height - Seated (Max)	-
Thickness (Max)	0.043" (1.10mm)
Lead Spacing	-

[Report errors?](#)

PFST.420 Guarantees



Quality Guarantees

We provide 90 days warranty. *

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



Service Guarantees

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

PFST.420 Payment Methods



PFST.420 Shipping Methods



If you have any question about PFST.420, please do not hesitate to contact us!

Website: <https://www.heisener.com>

E-mail: salesdept@heisener.com