

**PFST.420 Information**


For Reference Only

**Part Number** [PFST.420](#)  
**Manufacturer** Schurter Inc.  
**Category** Circuit Protection  
[PTC Resettable Fuses](#)  
**Description** FUSE PTC 4.20A 30V RESET AXIAL  
**Package** Strap  
 For the pricing/inventory/lead time, please contact us  
 Website: <https://www.heisener.com>  
 E-mail: [salesdept@heisener.com](mailto:salesdept@heisener.com)


[Request a Quote](#)
**Certified Quality**

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.


**PFST.420 Specifications**

Manufacturer Part Number	<a href="#">PFST.420</a>
Manufacturer	Schurter Inc.
Category	Circuit Protection <a href="#">PTC Resettable Fuses</a>
Package	Strap
Series	PFST
Type	Polymeric
Voltage - Max	30V
Current - Max	100A
Current - Hold (Ih) (Max)	4.2A
Current - Trip (It)	7.6A
Time to Trip	6s
Resistance - Initial (Ri) (Min)	12 mOhms
Resistance - Post Trip (R1) (Max)	40 mOhms
Resistance - 25°C (Typ)	-
Operating Temperature	-40°C ~ 85°C
Ratings	-
Mounting Type	User Defined
Package / Case	Strap
Size / Dimension	1.240" L x 0.522" W (31.50mm x 13.25mm)
Height - Seated (Max)	-
Thickness (Max)	0.043" (1.10mm)
Lead Spacing	-

[Report errors?](#)

## PFST.420 Guarantees



### Quality Guarantees

We provide 90 days warranty. \*

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



### Service Guarantees

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

## PFST.420 Payment Methods



## PFST.420 Shipping Methods



If you have any question about PFST.420, please do not hesitate to contact us!

Website: <https://www.heisener.com>

E-mail: [salesdept@heisener.com](mailto:salesdept@heisener.com)