

# PL138-98FC-R

#### PL138-98FC-R Information

	PL138-98FC-R Microchip Technology Integrated Circuits (ICs) Clock/Timing - Clock Buffers, Drivers IC CLK BUFFER 2:9 700MHZ 32LQFP 32-LQFP Exposed Pad For the pricing/inventory/lead time, please contact	
For Reference Only	us Website: https://www.heisener.com E-mail: salesdept@heisener.com	Request a Quote

## **Certified Quality**

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.



### PL138-98FC-R Specifications

Manufacturer Part Number	PL138-98FC-R	
Manufacturer	Microchip Technology	
Category	Integrated Circuits (ICs)	
	Clock/Timing - Clock Buffers, Drivers	
Package	32-LQFP Exposed Pad	
Series	-	
Туре	Fanout Buffer (Distribution), Multiplexer	
Number of Circuits	1	
Ratio - Input:Output	2:9	
Differential - Input:Output	Yes/Yes	
Input	CML, HCSL, LVCMOS, LVDS, LVHSTL, LVPECL, SSTL	
Output	LVPECL	
Frequency - Max	700MHz	
Voltage - Supply	2.375 V ~ 3.63 V	
Operating Temperature	$0^{\circ}\mathrm{C} \sim 70^{\circ}\mathrm{C}$	
Mounting Type	Surface Mount	
Package / Case	32-LQFP Exposed Pad	
Supplier Device Package	32-LQFP (7x7)	
	Re	eport errors?

#### PL138-98FC-R Guarantees



Quality Guarantees

We provide 90 days warranty. \* If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.

# SERVICE EUARANTEE

#### **Service Guarantees**

We guarantee 100% customer satisfaction. Our experienced sales team and tech support team back our services to satisfy all our customers.

#### PL138-98FC-R Payment Methods



#### PL138-98FC-R Shipping Methods



If you have any question about PL138-98FC-R, please do not hesitate to contact us! Website: https://www.heisener.com E-mail: salesdept@heisener.com