

**PL138-98FC Information**


For Reference Only

**Part Number** [PL138-98FC](#)  
**Manufacturer** Microchip Technology  
**Category** Integrated Circuits (ICs)  
[Clock/Timing - Clock Buffers, Drivers](#)  
**Description** IC CLK BUFFER 2:9 700MHZ 32LQFP  
**Package** 32-LQFP Exposed Pad  
 For the pricing/inventory/lead time, please contact us  
 Website: <https://www.heisener.com>  
 E-mail: [salesdept@heisener.com](mailto:salesdept@heisener.com)


[Request a Quote](#)
**Certified Quality**

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.


**PL138-98FC Specifications**

Manufacturer Part Number	<a href="#">PL138-98FC</a>
Manufacturer	Microchip Technology
Category	Integrated Circuits (ICs) <a href="#">Clock/Timing - Clock Buffers, Drivers</a>
Package	32-LQFP Exposed Pad
Series	-
Type	Fanout Buffer (Distribution), Multiplexer
Number of Circuits	1
Ratio - Input:Output	2:9
Differential - Input:Output	Yes/Yes
Input	CML, HCSL, LVCMOS, LVDS, LVHSTL, LVPECL, SSTL
Output	LVPECL
Frequency - Max	700MHz
Voltage - Supply	2.375 V ~ 3.63 V
Operating Temperature	0°C ~ 70°C
Mounting Type	Surface Mount
Package / Case	32-LQFP Exposed Pad
Supplier Device Package	32-LQFP (7x7)

[Report errors?](#)

## PL138-98FC Guarantees



### Quality Guarantees

We provide 90 days warranty. \*

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



### Service Guarantees

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

## PL138-98FC Payment Methods



## PL138-98FC Shipping Methods



If you have any question about PL138-98FC, please do not hesitate to contact us!

Website: <https://www.heisener.com>

E-mail: [salesdept@heisener.com](mailto:salesdept@heisener.com)