

SCA100T-D01-1 Information


For Reference Only

Part Number [SCA100T-D01-1](#)
Manufacturer Murata
Category Sensors, Transducers
 [Motion Sensors - Inclinometers](#)
Description INCLINOMETER 2-AXIS 30DEG 12SMD
Package 12-SMD, L-Bend
 For the pricing/inventory/lead time, please contact us
 Website: <https://www.heisener.com>
 E-mail: salesdept@heisener.com


[Request a Quote](#)
Certified Quality

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.


SCA100T-D01-1 Specifications

| | |
|--------------------------|--|
| Manufacturer Part Number | SCA100T-D01-1 |
| Manufacturer | Murata |
| Category | Sensors, Transducers Motion Sensors - Inclinometers |
| Package | 12-SMD, L-Bend |
| Series | - |
| Axis | X, Y |
| Measuring Range | ±30° |
| Sensitivity | 4V/g |
| Bandwidth | 8 ~ 28Hz |
| Voltage Rating | 4.75 V ~ 5.25 V |
| Output Type | Voltage |
| Interface | SPI |
| Package / Case | 12-SMD, L-Bend |
| Operating Temperature | -40°C ~ 125°C (TA) |

[Report errors?](#)

SCA100T-D01-1 Guarantees



Quality Guarantees

We provide 90 days warranty. *

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



Service Guarantees

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

SCA100T-D01-1 Payment Methods



SCA100T-D01-1 Shipping Methods



If you have any question about SCA100T-D01-1, please do not hesitate to contact us!

Website: <https://www.heisener.com>

E-mail: salesdept@heisener.com