

**SCA100T-D01-6 Information**


For Reference Only

**Part Number** [SCA100T-D01-6](#)  
**Manufacturer** Murata  
**Category** Sensors, Transducers  
[Motion Sensors - Inclinometers](#)  
**Description** INCLINOMETER 2-AXIS 30DEG 12SMD  
**Package** 12-SMD Module  
 For the pricing/inventory/lead time, please contact us  
 Website: <https://www.heisener.com>  
 E-mail: [salesdept@heisener.com](mailto:salesdept@heisener.com)


[Request a Quote](#)
**Certified Quality**

Heisener's commitment to quality has shaped our processes for sourcing, testing, shipping, and every step in between. This foundation underlies each component we sell.


**SCA100T-D01-6 Specifications**

Manufacturer Part Number	<a href="#">SCA100T-D01-6</a>
Manufacturer	Murata
Category	Sensors, Transducers <a href="#">Motion Sensors - Inclinometers</a>
Package	12-SMD Module
Series	SCA100T
Axis	X, Y
Measuring Range	±30°
Sensitivity	4V/g
Bandwidth	10Hz
Voltage Rating	4.75 V ~ 5.25 V
Output Type	Digital
Interface	SPI
Package / Case	12-SMD Module
Operating Temperature	-40°C ~ 125°C (TA)

[Report errors?](#)

## SCA100T-D01-6 Guarantees



### Quality Guarantees

We provide 90 days warranty. \*

If the items you received were not in perfect quality, we would be responsible for your refund or replacement, but the items must be returned in their original condition.



### Service Guarantees

We guarantee 100% customer satisfaction.

Our experienced sales team and tech support team back our services to satisfy all our customers.

## SCA100T-D01-6 Payment Methods



## SCA100T-D01-6 Shipping Methods



If you have any question about SCA100T-D01-6, please do not hesitate to contact us!

Website: <https://www.heisener.com>

E-mail: [salesdept@heisener.com](mailto:salesdept@heisener.com)